



Testing Facility:  
TYC BROTHERS INDUSTRIAL CO., LTD

**Test Component:** TYC 80-6165  
Modified Front Combination Lamp System  
For 1992-1995 Honda Civic Coupe & Hatchback

**Functionality:** Headlamp, Turn Signal, Parking, Side Marker & Reflex Reflector  
DOT SAE AHRI5PP2

**Report No:**

**Report Date:** July 05, 2004

**Report Summary**

**TESTS (FMVSS-108)**

**Photometric Test – Combination Front Lamp**

SAE J566	(Head Lamp).....	PASSED
SAE J222	(Parking).....	PASSED
SAE J588	(Front Turn Signal Lamp).....	PASSED
SAE J592e	.(Side Marker Lamp).....	PASSED
SAE J594f	(Reflex Reflector).....	PASSED

**Signature of Responsible Laboratory Official:**

*The subject Head light #80-6165-XX conforms to all photometric requirements of the U.S Federal Motor Vehicle Safety Standard (FMVSS) 108.*

**GENERA CORPORATION**

26 Centerpointe Drive Suite 100 • La Palma • CA • 90623 • Tel: (714) 522-6688 • Fax: (714) 522-2233